


序号	报告编号	发布日期	结论	影像资料
8	GX-B1451/20-3-25001	2025年1月9日	本次共检高压开关设备7台，7台高压开关设备所检项目合格。	
9	GX-B1451/20-3-25001	2025年1月13日	本次共检高压开关设备7台，7台高压开关设备所检项目合格。	
10	GX-B1322/21-3-25001~25005	2025. 1. 10	所检项目合格。	

11	GX-B1312/20-3-25001~25002	2025. 1. 9	所检项目合格。	
12	GX-B1404/20-3-25001	2025. 1. 10	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
13	GX-B1404/20-3-25002	2025. 1. 10	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

14	GX-B1404/20-3-25003	2025. 1. 10	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>		
15	GX-B1404/20-3-25004	2025. 1. 10	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>		
16	GX-B1404/20-3-25005	2025. 1. 10	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>		

17	GX-B1404/20-3-25006	2025. 1. 10	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>			
18	GX-B1404/20-3-25007	2025. 1. 10	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>			
19	GX-B1310/21-3-25001	2025年1月13日	<p>未发现超过Φ2mm当量直径的缺陷。</p>			

20	GX-B1310/21-3-25002	2025年1月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。		 2025.01.02	
21	GX-B1310/21-3-25003	2025年1月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。		 2025.01.02	
22	GX-B1310/21-3-25004	2025年1月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。		 2025.01.03	


23	GX-B1495/20-3-25001~25016	2025年1月13日	本次共检高压开关设备16台，16台高压开关设备所检项目合格。 。		
24	GX-B1612/23-3-24051	2025年1月13日	所检项目合格。		
25	GX-B1612/23-3-24052	2025年1月13日	所检项目合格。		

26	GX-B1612/23-3-24053	2025年1月13日	所检项目合格。			
27	GX-B1612/23-3-24054	2025年1月13日	所检项目合格。			
28	GX-B1612/23-3-24055	2025年1月13日	所检项目合格。			

29	GX-B1612/23-3-24056	2025年1月13日	所检项目合格。	 A person wearing a blue jacket, blue pants, and a blue hard hat stands in front of a yellow truck. The truck has a red and white bumper. The background shows a concrete area and a green wall. A yellow timestamp '2024.12.27' is visible at the bottom right of the photo.
30	GX-B1612/23-3-24057	2025年1月13日	所检项目合格。	 A person wearing a blue jacket, blue pants, and a blue hard hat stands in front of a yellow truck. The truck has a red and white bumper. The background shows a concrete area and a green wall. A yellow timestamp '2024.12.27' is visible at the bottom right of the photo.
31	GX-B1612/23-3-24058	2025年1月13日	所检项目合格。	 A person wearing a blue jacket, blue pants, and a blue hard hat stands next to a yellow truck. The truck has a red and white bumper. The background shows a concrete area and a green wall. A yellow timestamp '2024.12.27' is visible at the bottom right of the photo.

32	GX-B1612/23-3-24059	2025年1月13日	所检项目合格。		
33	GX-B1612/23-3-24060	2025年1月13日	所检项目合格。		
34	GX-B1612/23-3-24061	2025年1月13日	所检项目合格。		

35	GX-B1612/23-3-24062	2025年1月13日	所检项目合格。		
36	GX-B1612/23-3-24063	2025年1月13日	所检项目合格。		
37	GX-B1612/23-3-24064	2025年1月13日	所检项目合格。		

38	GX-B1612/23-3-24065	2025年1月13日	所检项目合格。			
39	GX-B1612/23-3-24066	2025年1月13日	所检项目合格。			